Anniston Army Depot
Lean Six Sigma - Success Story
AGT 1500 Rear Module Assembly

- Established Standard Work Cells
- Realigned Work Area
  - Hoist Relocation Reduced Rear Module Assembly ≈ 2.2 MH
- Instituted Inspection & Routing to Repair Prior to Routing to Assembly

Rear Module Assembly

Rear Module Assembly